



























X/y  Punkt logiczny  
 X/y  2xRJ45 (X-nr panela, y- nr modułu)



# PIĘTRO II




4/17   
 4/18   
 4/15   
 4/16   
 4/13   
 4/14   
 Pok.  
 lekarski  
 4/11   
 4/12   
 4/21   
 4/22   
 4/23   
 4/24 

5/1   
 5/2   
 5/3   
 5/4   
 5/5   
 5/6 

 4/9  
 4/10

Gab.  
 diagnostyczno  
 zabiegowy  
 4/7  
 4/8

 4/5  
 4/6  
 Lekarz  
 dyżurny

Pok.  
 ordynatora  
 4/1   
 4/2   
 4/3   
 4/4 